

SMDK2410 Revision History (Main Board Required)

August 19, 2002

PCB	PBA	Description (Only Required)	Date
Ver : 0.0 (20020315)	A	First production for development	-
	B	Touch Screen is fixed function 1) Pattern Cutting - U28-4 Pin between Via Hole - CON7-39 Pin between CON18-9Pin. 2) Wire connection - CON18-8Pin to CON7-39Pin , CON7-39Pin to CON8-1Pin 3) Shunt Setting : CON18 1-2	On the 10th of April
Ver : 1.0 (20020417)	B		
	C	First release to customer	
	D	SD Card Write Protect/Card Detect CON11 (SD Card) Body pad between GND is wiring. Write Protect : CON11-10Pin between TP3 (Port UCLK/GPH8) is wiring. Card Detect : CON11-11Pin between U4-18 (Port EINT18/GPG10) is wiring.	On the 9th of May
Ver : 1.1 (20020509)	A		On the 22th of May
	B	EPM7032 pin #11 nFCE confliction problem. The pin #11 of SMDK2410 V1.1 EPM7032(U4) is conflict with nFCE signal of S3C2410X. Because of the mistake of EPM7032 coding, the pin #11 is driven as 'L' and S3C2410X drives the nFCE as 'H'. So, the current consumption becomes big and the S3C2410X will get heated. Solutions: 1) In the SMDK2410 V1.1 after 2.JUN.2002(S/N:2410xxxxxxx B), this problem has been fixed. 2) In the SMDK2410 V1.1 before 2.JUN.2002(S/N:2410xxxxxxx A), If you have a Altera byte blaster, re-program the EPM7032 as the attached .pof file. If you don't have a Altera byte blaster, make the pin #11 of EPM7032 float.	On the third of June
Ver : 1.2 (20020603)	A		On the 22th of June
	B	SD Card (Added 10 Kohm pull up register) R106, R107, R113, R114, R115, CON11-10Pin (or TP3) between VDD33V.	On the 5th of July
Ver : 1.3 (20020703)	A	Enhance MCU operation performance nBUSY signal of SmartMedia card socket can connected with RnB and nWait by positioning jumper J2. To satisfy this, following contents are changed. - J2 is changed from 2 pin to 3 pin type	On the 25th of July

* Note : PBA Version , S/N:241022xxxxxx **A**

Please, The Board revision and A/S are contacted with AIJI System.(Tel. 82-31-223-6611)