

**September 11, 2006****Errata Document for CY7C65620/30, EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family**

This document describes the errata for the EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family, CY7C65620/30. Details include errata trigger conditions, scope of impact, available workarounds, and silicon revision applicability. Compare this document to the device's data sheet for a complete functional description.

Contact your local Cypress Sales Representative if you have HX2LP questions.

Part Numbers Affected

Part Number	Device Characteristics
CY7C65620	All Packages
CY7C65630	All Packages

HX2LP Qualification Status

Product status: Sampling

HX2LP Errata Summary

No errata items.

References

[1] Document # 38-08037, CY7C656XX EZ-USB HX2LPTM Low-Power USB 2.0 HUB Controller Family



Document History Page

Document Title: EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family Document Number: 001-099068 Rev. **				
REV.	ECN NO.	Issue Date	Orig. of Change	Description of Change
**	501609	See ECN	KKU	Original release of spec