


PART NUMBER	CATALOG NUMBER	DESCRIPTION	UPC CODE
00940037Z	094037	ACS FUSE CADDY ASST	0 79458 00691

SERVICEMAN'S FAVORITE ASSORTMENT CONTAINING THE FOLLOWING FUSES, TO BE PLACED IN 896-075 BOX & 896-220 SLEEVE, IN SEQUENCE SHOWN BELOW, LEAVING ONE SECTION EMPTY, IN EACH ROW AT FRONT OF BOX.

- |                                  |                                  |                                |
|----------------------------------|----------------------------------|--------------------------------|
| 1 BOX - 0312.500VXP (3AG 1/2A)   | 1 BOX - 0312003.VXP (3AG 3A)     | 1 BOX - 0313002.VXP (3AG 2ASB) |
| 1 BOX - 0312001.VXP (3AG 1A)     | 1 BOX - 0312003.VXP (3AG 3A)     | 1 BOX - 0313002.VXP (3AG 2ASB) |
| 1 BOX - 031201.5VXP (3AG 1 1/2A) | 1 BOX - 0312005.VXP (3AG 5A)     | 1 BOX - 0313003.VXP (3AG 3ASB) |
| 1 BOX - 0312002.VXP (3AG 2A)     | 1 BOX - 0313.500VXP (3AG 1/2ASB) | 1 BOX - 0313003.VXP (3AG 3ASB) |
| 1 BOX - 0312002.VXP (3AG 2A)     | 1 BOX - 0313001.VXP (3AG 1ASB)   | 1 BOX - 0313005.VXP (3AG 5ASB) |
| EMPTY SECTION                    | EMPTY SECTION                    | EMPTY SECTION                  |

ONE LABEL 890-063 TO BE ATTACHED TO OUTSIDE OF BOX BOTTOM AND POSITIONED SO THAT PRINTING IS VISIBLE THROUGH OPENED BOX AND CORRESPONDS TO THE ORDER OF FUSE PACKING LISTED ABOVE. PUT ASSEMBLED BOX IN SLEEVE AND LABEL TOP OF SLEEVE WITH 914-020 PRINTED AS SHOWN:



PACK 30 COMPLETED UNITS INTO OVERPACK CARTON 580249, CLOSE AND SEAL WITH TAPE. LABEL WITH PART NUMBER AND QUANTITY. IF PACKED AT LITTELFUSE USE LABEL 914-796, PRINTED TO LABEL SPECIFICATION LS-000003.

914-020	LABEL	1000	EAD
-	LABEL	1000	EA
-	LABEL	1000	EA
-	SLEEVE	1000	EA
-	CADDY BOX	1000	EA
-	CARTON	33.33	EAD
11	3AG SLO BLO FUSE: 5 AMP	5000	EA
10	3AG SLO BLO FUSE: 3 AMP	10,000	EA
9	3AG SLO BLO FUSE: 2 AMP	10,000	EA
8	3AG SLO BLO FUSE: 1 AMP	5000	EA
7	3AG SLO BLO FUSE: 1/2 AMP	5000	EA
6	3AG FAST ACTING FUSE: 5 AMP	5000	EA
5	3AG FAST ACTING FUSE: 3 AMP	10,000	EA
4	3AG FAST ACTING FUSE: 2 AMP	10,000	EA
3	3AG FAST ACTING FUSE: 1 1/2 AMP	5000	EA
2	3AG FAST ACTING FUSE: 1 AMP	5000	EA
1	3AG FAST ACTING FUSE: 1/2 AMP	5000	EA
NO	DESCRIPTION	QTY/M	U/M

**BILL OF MATERIAL**

COPIES TO		MATERIAL SPEC			FINISH	
1	9	DRW	PJM	DATE	07/02/01	SCALE
2	10	CHK		DATE		SUPER DRW
3	12	APPD		DATE		RAW STK WT
4	13					LBS/M
5	14					
6	15					
7	16					
8	17					
18	18					
19	19					
20	20					
21	21					
22	22					
23	23					
24	24					
25	25					
26	26					
27	27					
28	28					
29	29					
30	30					

**REVISION**

LTR	REVISION	CHK	APD
N	81441B-REVISE & REDRAW IN NEW FORMAT 07/02/01 PJM		
P	000233EC/B-CHG V TO VXP 09/18/07 PJM		

**TITLE**

SERVICEMAN'S FAVORITE ASSORTMENT	REVISION	00940037Z	FINAL
Littelfuse		DRWG. NO.	
DES PLAINES, ILLINOIS 60016			

UNLESS OTHERWISE SPECIFIED, DIMENSIONS DO NOT INCLUDE PLATING.  
 DENOTES CRITICAL CHARACTERISTICS.  
 DENOTES CPK DIMENSIONS, -MINIMUM CPK VALUE  
 DENOTES A CHARACTERISTIC THAT PROVIDES AN INDICATION OF PROCESS PERFORMANCE. PROCEDURE FOR MEASUREMENT AND TRACKING TO BE DEFINED IN LITTELFUSE INSPECTION INSTRUCTIONS.  
 DENOTES CP DIMENSIONS, -MINIMUM CP VALUE MUST BE WITHIN THE DIMENSIONAL LIMITATIONS SHOWN ON DRAWING AND INITIALLY LOCATED TO ALLOW FOR MAXIMUM TOOL LIFE.

