

Fiber Optic Products

Fiber Optic Cable Assemblies

AMP 504678-7 Active [Active](#)

[Not Reviewed for ELV/RoHS Compliance](#)

(Tyco Electronics P/N: 504678-7)

[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information

General Information	eCommerce	Related Part Information
General Info	Pricing	Tooling
Sales Info	Product Availability	
Assembly Subcontractors		

Photos & Line Drawings - The photographs and/or line drawings are representative images of a product for viewing purposes only.

[Product Photo](#)

Searchable Features:

Brand:	AMP
Product Type:	Cable Assembly
Cable Assembly Type:	SC-APC to SC-APC
Fiber Type:	SMF-28
Mode:	Singlemode
Cable Type:	Buffered Fiber
Cable Diameter (mm [in]):	900 micron [900 micron]
No. of Fibers:	1
Cable Buffering:	Tight
Cable Color:	White
Length (M [ft]):	20.00 [65.62]

Other Properties:

AMP Logo:	With
Insertion Loss (dB):	0.50
Return Loss (dB):	65

Mode Conditioned Launch Cable Assembly:	No
Connector(s) Exit Angle to Connector(s) Exit Angle:	180° to 180°
Boot Body Style - Left:	Long
Boot Color - Left:	Green
Boot Body Style - Right:	Long
Boot Color - Right:	Green
Ferrule Material:	Ceramic
Fibre Channel:	No

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

