

This drawing is the property of Greenpar Connectors, and must not be copied or disclosed to a third party without written permission.


Third angle projection

greenpar
CONNECTORS

GOLD FINISH	MARKING
GEX	X

920	1.00 M	BLANK
-----	--------	-------

"X" OVERALL LENGTH



Item	Description	Quantity
10	CABLE	X
9	STRAIN RELIEF	2
8	CRIMP SLEEVE	2
7	FERRULE	2
6	REAR INSULATOR	2
5	BODY	2
4	MALE CONTACT	2
3	FRONT INSULATOR	2
2	CIRCLIP	2
1	SLEEVE	2

© ENSURE TURNOVER TOOL DOES NOT CLIP EDGES OF BARB ON FERRULE.

General Instructions Dimensions to be concentric unless otherwise noted Remove all burrs and sharp edges Dimensions are after plating Plating allowance code Machining symbols		Tolerance Fractions $\pm 1/64"$ Angles $\pm 1^\circ$ All dimensions in inches unless stated otherwise		Material For finish, refer to Assembly parts list		Revision 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100		Date 29-11-85		Title CABLE ASSEMBLY Part number GEX 920 Scale 5/1	
---	--	--	--	--	--	--	--	------------------	--	---	--