

Model CLSM-100S Closed Loop Hall Effect

Description

The Model CLSM-100S is a closed loop Hall effect current sensor that accurately measures DC and AC currents and provides electrical isolation between the current carrying conductor and the output of the sensor.

Features

- Noncontact measurement
- Measures DC, AC and impulse currents
- Very fast response and high accuracy
- High overload capacity

Applications

- Variable speed drives for motors
- Welding Equipment
- Power supply Equipment
- Measure and control system
- Over current protection
- Protection of power semiconductors



Electrical Specifications

CLSM-100S

Nominal current (I_N)	$\pm 100 \text{ A}$
Current range	0 to $\pm 200 \text{ A}$
Nominal output current (I_M)	50 mA
Turns Ratio	2000 / 1
Measuring Resistance (R_M)	0 to 100 Ω
Overall accuracy at 25°C	$\pm 0.5\%$ of I_N
Supply voltage (Vdc).....	± 12 to ± 18
Current consumption	15 mA + output current

Accuracy-Dynamic Performance

Zero current offset at 25°C	< $\pm 0.2\text{mA}$
Offset current temperature drift (-25°C to $+85^\circ\text{C}$)	< $\pm 0.3\text{mA}$
Linearity	better than $\pm 0.1\%$
Response time	better than $0.5\mu\text{s}$
di / dt	better than $70\text{A}/\mu\text{s}$
Frequency range	DC to 200KHz (-3dB)

General Information

Operating temperature	-25°C to +85°C
Storage temperature	-40°C to +100°C
Package	flame retardant plastic case, UL94V-0
Isolation voltage	5kV/50Hz/min.
Output reference.....	To obtain a positive output on terminal M, input current must flow in the direction of the arrow (conventional flow)
Weight	28 grams
Mounting	Designed to mount directly on PCB via through hole connection pins
Aperture size (mm).....	7 x 16

Notes:

1. Busbar temperature should not exceed 100°C.
2. The dynamic performance is the best when the busbar fills the aperture.
3. Due to continuous process improvement, all specifications are subject to change without notice.



SYPRIS

TEST & MEASUREMENT


6120 Hanging Moss Road • Orlando, Florida 32807 • www.fwbell.com
Phone (407) 678-6900 • Fax (407) 677-5765 • Toll Free (800) 778-6117

Mechanical Dimensions


All dimensions are in inches (millimeters)

Model CLSM-100S

Mechanical Dimensions



Connection Schematic



Note: Due to continuous process improvement, all specifications are subject to change without notice.