

RF Connectors**Between Series Adapters (BSA's)****AMP** **1060425-1** **Active** [Active](#)[Not Reviewed for ELV/RoHS Compliance](#)**(Tyco Electronics P/N: 1060425-1)**[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information

General Information	eCommerce	Related Part Information
☐ General Info ☐ Sales Info ☐ Assembly Subcontractors	☐ Pricing ☐ Product Availability	☐ Tooling

Searchable Features:

Brand:	AMP
RoHS/ELV Compliance:	Not reviewed for compliance
Gender:	Plug
Adapter Type:	SMB

Other Properties:

Mount:	Flange Mount
Housing Material:	Brass
Housing Finish:	Gold
Center Contact Material:	Beryllium Copper
Center Contact Plating:	Gold
Dielectric Material:	TFE Fluorocarbon
Retaining Ring Material:	Beryllium Copper
Retaining Ring Finish:	Gold
Comment:	4-Hole Flange Mount Plug Receptacle Solder Pot Terminal

- ☐ [Home](#)
- ☐ [Part Number Search](#)
- ☐ [Document Search](#)
- ☐ [CAD Model Search](#)
- ☐ [Text Search](#)
- ☐ [Alternate/Lead Free Part Search](#)
- ☐ [Multiple Part Comparison](#)
- ☐ [Alphabetical Search](#)
- ☐ [Brand Search](#)
- ☐ [Industry Product Search](#)
- ☐ [Product Type Search](#)
- ☐ [Product Family Search](#)
- ☐ [Competitor Cross Reference](#)
- ☐ [Lead Free Solutions](#)
- ☐ [Tool Search](#)
- ☐ [Help/Glossary](#)

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

